


















			M3	M4	M5	M6	M8	M10	M12	M14	
<b>Aparatos de colocación manuales</b>	RIVKLE® BRK 01		■	■	■	■					49
	RIVKLE® M2007				★	★	★	★	★		49
	RIVKLE® BRK 10				■	■	■	■			50
	RIVKLE® ES 51					■	■	■	■	■	50
	RIVKLE® OPTEX				■	■	■				50
<b>Máquinas de colocación oleoneumáticas</b>	RIVKLE® P2005		■	■	■	■	■	■	■		52
	RIVKLE® P1007		■	■	■	■					52
	RIVKLE® P2007			■	■	■	■	■			53
	RIVKLE® B2007		■	■	■	■	■	■			53
	RIVKLE® P3007						■	■	■	■	54
	RIVKLE® P2007 PN			★★	★★	★★	★★				54
	RIVKLE® P3007 PN						★★	★★			54
	RIVKLE® EPX009		■	■	■	■	■	■	■	■	55
<b>Equipos especiales semiautomáticos</b>	RIVKLE® EPK C			■	■	■	■	■			59
	RIVKLE® EPK HP						■	■	■	■	59
<b>Equipos especiales automáticos</b>	RIVKLE® HSA 2.0			■	■	■	■	■			59
	RIVKLE® ESA 2.0				■	■	■				59

★ RIVKLE® PN

★★ RIVKLE® & RIVKLE® PN